

PropIO V2 Errata for Board Version 2.00

- Capacitor C21 was originally specified as 33uF. I now recommend 220uF. This change has been reflected in the posted parts list and BOM.
- The board contains an error which omits +5V to the LM3940 voltage regulator. The patch below will correct this. This patch applies **only** to v2.00.

