Mandatory update:
     Version 1.0-005 board to version 1.1   15-Aug-2105

Install a 1/2" wire from:
     U407 pin 1   GAL22v10-BYTES9
to:
     U405 pin 21   GAL22v10-DRAM9

After installing this wire, the board is still operable. However, to obtain the benefit of this update, U405 GAL should be updated to DRAM9-03. See the accompanying PLD file of this date.

The update of U407 GAL to BYTES9-03 is optional. BYTES9-02 is still current.

Place a sticker on the board to indicate that the update to version 1.1 has been installed.

--John Coffman
<johninsd@gmail.com>