
Subject: Re: CB030, A 68030 SBC for hobbyists
Posted by [mikemac](#) on Fri, 17 Jul 2020 01:03:37 GMT
[View Forum Message](#) <> [Reply to Message](#)

I'm guessing either your SIMM is bad or your initrd.gz image is corrupted. I had issues with my SIMM too and it would result in seemingly random failures.
