

---

Subject: Re: All: Please review verilog code  
Posted by [lynchaj](#) on Mon, 27 Jun 2016 18:36:38 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Hi

Yes, there is something weird going on in the printing of the PDF because those pin pads are present in the PCBnew tool. I will investigate and try to figure out what is happening. More on this soon. Thanks

Andrew Lynch

---