

---

Subject: Re: CB030, A 68030 SBC for hobbyists  
Posted by [mikemac](#) on Sat, 07 Mar 2020 03:18:45 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

plasma wrote on Fri, 06 March 2020 18:09Ouch, that's no good. Looked up MT4LC16M4H9 and it is 3.3V part, not 5V tolerant. That was a 3.3V 64meg SIMM and probably not doing it any good plugging into a 5V system.

Bill

I'll give them a call tomorrow or Monday and see if they'll straighten it out. It's not the nine dollars as much as the missed opportunity of having it this weekend for pimping out my CB030 board. I can still make progress with the 16MB. Just disappointing.

---