
Subject: Re: MiniMax8085 - Extension Board
Posted by [Sergey](#) on Wed, 26 Jan 2022 16:05:03 GMT
[View Forum Message](#) <> [Reply to Message](#)

Alank2, that was the idea... When I get some free time.
Unless someone else wants to take a stab at it.
It shouldn't be too difficult. One possible issue is the lack of storage devices, which can be resolved by using the PPI serial port to attach one (e.g. PPIDE).
